


GLOVE SIZING GUIDE

Two methods of checking your glove size

OPTION 1: MEASURE HAND


Using a string or measuring tape, measure the circumference around the knuckles, excluding the thumb. Your hand should be open with the fingers together. Compare this measurement to the chart below to determine your glove size.



5/XXS	6/XS	7/S	8/M	9/L	10/XL	11/XXL	12/3XL
12-15cm	18-19cm	19-20cm	20-21.5cm	21.5-23cm	23-25cm	25-28cm	28-30cm

OPTION 2: SIZING CHART

Place your right hand on the glove chart so that the saddle of your thumb and index finger line up with the X. The measurement closest to the right edge of your hand will be the appropriate glove size.



Industrial gloves inevitably have varied size ranges, and this is because of the materials needed to provide adequate and specific protection. We recommend using our size charts, reviewing glove descriptions and materials, and if you are still uncertain about what size would best fit your hand, give us a call at 0800 500 470.